Comfortable workplaces

# Lighting

There shall be no burned-out bulbs, flickering, or other problems with indoor light fixtures.



# 13 perspectives on health and safety measures

Prevention from toppling over and fall prevention

## **Fall prevention**

No items that could be dangerous if dropped shall be placed on cabinets, shelves, etc. in the room.



Ventilation and air conditioning shall be in good working order, temperature and humidity shall be appropriate (18 to 28°C, 40 to 70%), and there shall be no unusual odors

Comfortable workplaces

### Water area

Sinks, etc. shall be clean and free of damage, leaks, dirt, mold or the like.

Fire prevention measures

#### **Combustibles**

No flammable materials shall be placed near fire.



Gas appliances and hoses shall be properly connected with fixtures and shall not be deteriorated or damaged.

Fire prevention measures

## Overloaded electrical wiring

No overloaded electrical wiring or the like shall be allowed, and the allowable power shall not be exceeded.

Fire prevention measures

#### Power plug

There shall be no damage to electrical cords, outlets, etc., and no dust accumulation on the outlets.

## **Prevention** of stumbling

Securing passageways

Power cords, cables, etc. shall not obstruct traffic. Prevention from toppling over and fall prevention

## **Prevention** from toppling over

Cabinets, shelves, etc. (especially with a height of 150 cm or more) in the room shall be fixed with L-shaped brackets, etc.

**Securing evacuation routes** 

#### **Entrance / Exit**

There shall be no objects or other items placed near entrances or exits that could hinder evacuation.

**Securing evacuation routes** 

## **Passageway**

No objects shall be placed in the interior passageways that would hinder passage or evacuation.

**Keeping things sorted** and in order

#### Cleanup

Rooms shall be cleaned regularly and kept sorted and in order.

